

# FAILED PINION

*(front part)*



# ONE OF NINE DRIVE PINIONS



# FAILED PINION

*(Front Part)*



# FAILED PINION

*(Rear Part)*




# BROKEN MAIN GEAR TOOTH

*Found during initial inspection*



Crushed and indentation caused by broken pinion running out of mesh with main gear

# BROKEN PINION GEAR TOOTH




Top of tooth damaged by main gear when out of mesh

# BROKEN PINION GEAR TOOTH



Chunk of gear tooth and broken support bearing outer race

# DRIVE MOTOR GEAR BOX



Assembly and pinion removed to show damaged teeth of main gear



# DAMAGED GEAR TEETH ON MAIN GEAR



# SPLINED DRIVE SHAFT




One end connects to gear box and other end connects to the splined pocket of the drive pinion

# SPLINED SHAFT



Mounted in gear box output

# SPLINED POCKET



Splined pocket of pinion receives drive shaft connected to output of gear box

# SPLINED DRIVE SHAFT OF BROKEN PINION



Destroyed when pinion failed

# INSIDE MAIN BEAM

*Looking out front of TBM*



Cutterhead has been removed and bolted to the tunnel face.

# Bearing Bypass Cavern

*In tunnel side wall*



Blasted 300 ft.  
from tunnel face  
behind TBM  
trailing gear

# Bearing Bypass Chamber



Housing new main bearing and man-lift



# ROCK BOLTS & STRAPS



Supporting roof bypass cavern

# FRACTURED ROCK



- Fractured rock above Bypass cavern prevent TBM gripper from being used to walk past cavern.
- A “walking shoe” was fabricated and bolted to the tunnel floor.

# WALKING SHOE



Walking shoe attached to tunnel floor allows moving TBM without using the gripper as it moves past bearing bypass cavern

# Bypass Cavern

*Looking back from face*



Note: gripper shoe is off the wall

# OVERHEAD MONORAIL SYSTEM



50 ton monorail system to lift and move main bearing

# MAIN BEARING



Damaged main bearing removed from TBM on 8/16/06