

Levee Failures Along the Inner Harbor Navigation Channel in New Orleans

J. David Rogers, Ph.D., P.E., P.G.

Missouri University of Science & Technology

for Technical Session #15 on

New Orleans Levees and Hurricane Katrina


Annual Meeting


**Association of Environmental &
Engineering Geologists**

New Orleans

Sept. 19, 2008

Online at: www.mst.edu/~rogersda








- **The 6-mile long Industrial Canal runs between the Mississippi River and Lake Pontchartrain**
- **It was excavated by centrifugal dredges, beginning in May 1918**
- **Funded by \$6 million bond passed in 1914**
- **Work commenced in May 1918. Berths off the Mississippi River allowed private frontage to be leased for exclusive use of industrial clients**
- **A series of diagonal slips were envisioned; as was an 18 month construction schedule**

Original Intent


- The lower third of the IHNC was intended to provide private wharf frontage for industrial warehouses, as shown here
- During the first 25 years, only one tenant purchased space, on the west side of the IHNC






The IHNC was dredged as a trapezoidal channel with a single lock, in two sequences of excavation, undertaken between 1918-23. In Section III the channel was 330 feet wide, with a maximum depth of 30 feet over 150 feet. Side cast hydraulic fill formed levees on either side of the excavation.

Stratigraphy in Vicinity of the IHNC Lock Structure



- Construction of the IHNC lock structure in 1919-23 proved troublesome, requiring 6 sheetpile bulkheads with raker braces and 6 rows of dewatering wells, with 5 monitoring wells along the centerline.
- Most of the problems were with two sequences of “running sands”



- After 5 years of construction costing \$20 million the IHNC was finally completed on May 5, 1923

GIWW




The GIWW was cut in 1944, during WW2. The excavation of diagonal slips shown here occurred during the mid-1950s, before the MRGO was excavated in 1960-64.




- **Aerial oblique view of the Inner Harbor Navigation Canal between 1960-64, after the entry to the Mississippi River-Gulf Outlet Channel had been enlarged (upper right), connecting to the inner harbor area.**



Discontinuous nature of stratigraphy underlying New Orleans



- The IHNC crossed thick sequences of point bar sands adjacent to the Mississippi River, then historic marshes (lowland backswamp), crossed the Gentilly-Sauvage distributary ridge, and thence into backswamps, before connecting to Lake Pontchartrain.



- The units lying beneath the IHNC channel vary from the west to the east side




■ Detail showing thickness of surficial peat in vicinity of the IHNC. Thickness varies from 0 to 12 feet along Section III, between Claiborne and Florida Avenues.

**OVERVIEW:
East Side IHNC
Failures
During Hurricane
Katrina**

East Side IHNC South Breach

Polluted and run-down industrial leases along east side of the IHNC were demolished and cleaned up in 2001-03, leaving exposed shell fill



Same area after re-flooding by Hurricane Rita in late September 2005




1965 flooding

The Lower Ninth Ward was flooded by overtopping of the levees along the IHNC in 1947 and 1965

The levee was heightened using rolled fill after both floods

Sheetpiles added after Hurricane Camille in 1969



Lower Ninth Ward



- **Aerial view of the 900 ft long south breach of the Inner Harbor Navigation Channel (IHNC) in the Lower Ninth Ward. View looking south.**



- **ING 4727 was built in 1990 as a dry cargo cover-top barge with a steel hull. It was 200 feet long, 35 feet wide, and 12 ft high, with a cargo volume of 84,659 ft³ (1877 tons). It was being leased to Lafarge North America and was tied up along the MRGO-IGWW channel.**



10.04.2005 12:24

- **Damage to concrete flood wall where ING 4727 Barge collided with it, along the south side of the IHNC adjacent to the Lower Ninth Ward**



- Evidence of sustained overtopping of concrete flood wall along the IHNC in the Lower Ninth Ward. Scour holes usually limited to 1.5X height of the free fall (7.5 ft). This scour trench deepened to the north, as elevations dropped.



- **Overtopping-induced failure of the flood wall on the west side of the IHNC, north of Florida Ave. This breach was only 65 feet wide.**

**ANALYSES:
East Side IHNC
North Breach**

East Side IHNC North Breach






East Side IHNC North Breach, near Florida Ave. bridge and pumping station, during inflow. Note narrow chasm defined by this failure and dramatic flexure of the sheetpiles.



**East Side IHNC North Breach, after de-watering.
Note tunnel-like geometry of this narrow breach**

Shear Strength under Toe




Undrained shear strength vs depth at the East IHNC North Breach

Blue lines shows profile of CPT-1, with NGI tip corrections for the three units encountered

Green line shows strength profile selected by the NSF team


Red lines shows strength profile used by the IPET team; which allows a rotational stability failure sometime between 5:30 and 6:00 AM

Slope Analysis IHNC North Breach



Critical stability conditions for East IHNC North Breach occur when the storm surge reaches +14 feet (MSL), which was not achieved until 9 AM. Note that the presumed failure surface passes through the marsh layer.

Hydrographs on IHNC



The storm surge caused by Katrina began three days before it made landfall, seen here as the gradual increase at left, about 0.32 ft/hr. Around midnight on August 29th, the rate increased 4X, to about 1.2 ft/hr . These rates and levels were used in our seepage analyses.

Boland Marine Site - EBIA




- **Upper-
Excavation of
contaminated
fine-grained
soils on water
side of IHNC
flood wall just
prior to
Katrina**
- **Lower -
Backfilling
with pervious
sand**




Old Cypress Swamp

- **The pre-Katrina excavations for the East Bank Industrial Area penetrated the old cypress swamp deposits, which lie beneath the IHNC levee and flood wall**






East Bank IHNC North Breach



Cross section used for limit equilibrium and coupled seepage analyses. Upper plot shows pore pressure versus horizontal distance and time for this section. Note modeling of pervious backfill at EBIA site.

Severe hydraulic gradients for piping and uplift



Hydraulic gradients for the north breach on IHNC. Storm surge at +14.4ft (MSL). Maximum exit gradient on the upper levee toe is $i_o \approx 1.0$, and $i_o \approx 1.5$ to 2.5 in the lower toe area. The distal toe value could have been worse, depending on k value of backfill used on Jourdan Ave. drainage canal.


Post Failure Analyses of East Side IHNC South Breach

Possible failure modes:


- Overtopping scour trench-induced flood wall failure; and
- Underseepage, piping and uplift induced translational stability failure
- Multiple failure modes likely competed with one another

ANALYSES: Stability of Flood Wall - East IHNC South Breach







Plaxis soft soil constitutive modeling of 7.5 ft deep scour trench and 4.5 ft gap – deformed mesh – true scale (max displacement of embankment crest = 1.2 ft)



Shear strains predicted by the Plaxis model, assuming a 7.5 ft deep scour trench and 4.5 ft wall gap – using “best estimates” of c and phi – Factor of Safety = 1.10. Underseepage-induced pore pressure trapped along base of less pervious clay stratum, overlying the more pervious marsh deposits.




**Leaning wall with 8.5 ft of gap – deformed mesh
– true scale (max displacement = 1.71 ft)**



Leaning wall with 8.5 ft of gap. Predicted shear strains using "best estimates" of c and phi. Factor of Safety now = 1.15

**Coupled
Seepage
Analyses of
Embankment
along East IHNC
South Breach**


East Bank IHNC South Breach



Geologic cross-section showing projections of borings and tentative stratigraphic correlations for the 800 ft long IHNC East Bank-South Breach, adjacent to the Lower Ninth Ward


Water squirted up adjacent boreholes when advancing Shelby tubes

Drill rig advancing Shelby tubes in backswamp deposits




- The porous and **highly conductive** nature of the backswamp deposits was revealed during post-Katrina drilling and sampling operations.
- Highly conductive in horizontal plane, especially, parallel to original surface drainage.

Anisotropy of backswamp deposits




- Sudden die-off of organics creates highly *anisotropic* fabric; preferentially layered



- Drainage swales in the backswamps are subject to sieving of fines by runoff
- This causes hydraulic conductivity to increase along the runoff path, as opposed to other seepage paths, within the plane of sediment accretion


MATERIAL	PARAMETER						
	γ (pcf)	ϕ	c (psf)	Kh (ft/hr)	Kh (cm/s)	Kv/Kh	Θ *
Fill	105	0	900	1.17E-04	9.91E-07	1	0.35
Upper CH	95	0	800	2.00E-04	1.69E-06	0.333	0.35
Upper Marsh	85	28	0	1.10E+00	9.31E-03	0.25	0.5
OC Grey CH	95	0	500	2.00E-04	1.69E-06	0.333	0.35
NC Grey CH	95	0	Su/p: 0.28	2.00E-04	1.69E-06	0.333	0.35
Lower Marsh	85	28	0	1.10E+00	9.31E-03	0.25	0.5
Silt	110	0	600	1.17E-04	9.91E-07	0.333	0.41
Lean Clay	100	0	600	2.00E-04	1.69E-06	0.333	0.38
Sands	120	30	0	1.00E+00	8.5E-03	0.5	0.42
Gaps				100		10	1

* Fredlund et al, Green and Corey, Van Genuchten




Geotechnical cross-section for conventional limit equilibrium and coupled seepage analyses of the east bank IHNC south breach.


Hydrographs on IHNC



The horizontal permeability in the pervious marsh deposits likely varies between 1×10^{-3} and 1×10^{-6} cm/sec., locally (within the marsh stratum), depending on a number of factors.




Finite difference mesh for seepage analyses for east bank IHNC south breach.



Pressure contours for the south breach on IHNC with storm surge at 14.4ft (MSL).

Hydraulic gradients for piping and uplift



- Hydraulic gradients for the south breach on IHNC east bank; storm surge at 14.4ft (MSL). Maximum exit gradient at the levee toe is $i_o \approx 0.8$ to 1.0, at threshold for hydraulic piping.

- This may help to explain the persistent wet spot noted on the backfill of the Jourdan Avenue conduit backfill for weeks afterward.



Aerial view of the south breach at the east bank of the IHNC (at the west end of the Ninth Ward), showing the 'wet spot' along the inboard side and the crevasse splay generated by reverse drainage flow. [Photograph by U.S. Army Corps of Engineers]

**Slope Stability
Analysis of
East IHNC
South Breach
Embankment**


Embankment Stability of East IHNC South Breach

ID	Soil Model	Name	Type	g_unsat [lb/ft ³]	g_sat [lb/ft ³]	k_x [ft/day]	k_y [ft/day]	nu [-]	E_ref [lb/ft ²]	c_ref [lb/ft ²]	phi [°]
CF Bottom	Mohr Coulomb	ML-silt (Compacted Fill)	Undrained	105	115	0.0028	0.00028	0.35	234000	900	0.001
		Gray Clay (bottom)	Undrained	90	90	0.0028	0.0028	0.3	155000	800	0.001


ID	Soil Model	Name	Type	g_unsat [lb/ft ³]	g_sat [lb/ft ³]	k_x [ft/day]	k_y [ft/day]	lambda* [-]	kappa* [-]	n_ur [-]	K0nc [-]	M [-]	c_ref [lb/ft ²]	phi @ pref [°]	OCR
M2	Soft Soil	Marsh 2	Undrained	80	80	28.3	2.8	0.21	0.033	0.15	0.60	1.90	0	36	1.1
M1		upper marsh	Undrained	80	80	28.3	2.8	0.2105	0.033	0.15	0.60	1.90	0.0001	36	2.25
ML		silt	Undrained	85	85	28.32	2.8	0.1	0.02	0.15	0.61	1.27	0.001	23	2
CH2		Gray Clay (CH)	Undrained	90	95	0.00028	0.00028	0.1684	0.03	0.15	0.63	1.24	0.0001	22	2.25-1.70
CH3		Gray Clay (CH)	Undrained	90	95	0.00028	0.00028	0.1684	0.03	0.15	0.63	1.24	0.001	22	1.1

ID	Name	Type	EA [lb/ft]	EI [lb/ft ²]	w [lb/ft ²]	nu [-]	M_p [lb/ft]	N_p [lb/ft]
1	I-wall	Elastic	6.32E+08	54290000	150	0.22	1.00E+15	1.00E+15
2	Sheetpile (Z-22)	Elastic	1.87E+08	16400000	22	0.22	1.00E+15	1.00E+15


Ignored backfilled drainage canal on inboard side




Geometry and input parameters for FEM (PLAXIS) stability analyses for Lower Ninth Ward, IHNC East Bank, South Breach.



Finite difference mesh for seepage analyses for east bank IHNC south breach.




Pressure contours for the south breach on IHNC with storm surge at 14.4ft (MSL).




Normalized shear strain contours (shear strain divided by strain to failure) for a storm surge at Elev. + 14 feet (MSL) on the east IHNC south breach; gapping at outboard toe of floodwall is fully developed.

Pore pressure vs Time on top of Lower Marsh - NO GAP




Estimated range in pore pressures at top of lower marsh unit assuming a range of horizontal hydraulic conductivity (k) in the marsh units, varying between 10^{-3} and 10^{-6} cm/sec

Pore pressure vs Time on top of Lower Marsh - GAP GENERATED




Estimated range in pore pressures at top of lower marsh unit *if the flood wall developed a gap*; assuming a range of horizontal hydraulic conductivity (k) in the marsh units, varying between 10^{-3} and 10^{-6} cm/sec

Pore pressure vs Time on top of Lower Marsh




Increase of pore pressure at top of lower marsh unit if the gap on water side of flood wall opened around 7:30 AM. This would have hastened the build-up of pore pressure at this location.

Slope stability – shallow failure mode (in upper marsh) – $FS=1.091$




Limit equilibrium analyses

Deep failure mode (in lower marsh) with wall gap- FS=0.985



This would appear to be the best explanation for a massive translational failure, 800 feet long.



Calculated Factors of Safety for three modes based on SLOPE/W analyses of the East Bank IHNC South Breach site for various surge levels; showing the best-estimated path to failure.

This lecture will be posted at

www.mst.edu/~rogersda/levees

**in .pdf format for easy downloading and
use by others.**