


with 8051

Instructions

tion

R0-R7 registers

Control Unit



WIMP51 Instructions

INSTRUCTION
MOV A, #data
MOV A, Rn
MOV Rn, A
ADDC A, #data
ADDC A, Rn
XRL A, Rn
ANL A, Rn
ORL A, Rn
SWAP A
SETB C
CLR C
SJMP rel
JZ rel

Tcl/Tk Interface

- Register value
- Dataflow high
- Optionally co